



LAWRENCE  
LIVERMORE  
NATIONAL  
LABORATORY

# B365 High Efficiency Particulate Air Filter Emergency Replacement An Example of Team Work

T. Coble, C. Little, R. Johnson

September 27, 2006

B365 High Efficiency Particulate Air Filter Emergency  
Replacement An Example of Team Work  
Livermore, CA, United States  
October 2, 2006 through October 3, 2006

This document was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor the University of California nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or the University of California. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or the University of California, and shall not be used for advertising or product endorsement purposes.

# **B365 High Efficiency Particulate Air Filter Emergency Replacement**

An Example of Team Work

October 2, 2006

Todd Coble  
Robert Johnson  
Christine Little

# Outline

- ISM
- Background of the facility
- Time line of events
- Team work- how it all came together
- Lessons Learned



# Building 365

- Research building
- 1 carcinogen research laboratory and 7 Biological research laboratory.
- Building exhaust system is HEPA filtered through a bank of six filters in parallel.
- Exhaust HEPA filter system is required for work in B365.

# Building HEPA Filter Exhaust System 6 Filters in Parallel



# Tuesday June 6th

- IHIL staff and H&S tech perform annual certification of HEPA's at Building 365.
- Discover HEPA filtration is good but pressure differential is unsatisfactory on 6 building exhaust HEPAs.
- The plenum ductwork on the exhaust side of the HEPAs is observed surging.

# Wednesday June 7th

- Receive test report.
- IHL staff retest differential pressure confirming failure of HEPAs.
- Rooms, hoods, and bio-safety cabinets posted immediately “No Work Allowed”. Building occupants informed.
- IH consults with CBS HEPA SME on possible options for HEPA fix.

The image shows a small, partially legible table or spreadsheet with multiple columns and rows. The text is very small and difficult to read, but it appears to be a data table with various columns and rows of information.

TO: Christine Little

HAZARDS CONTROL — INDUSTRIAL HYGIENE INSTRUMENT LAB  
HEPA FILTER TEST RESULTS

BLDG.: 365

PHOTOMETER HC # 0671

PAGE 1 OF 1

TEST/VISIT DATE 06/06/06

FILTER NO.	LOCATION	FAN NO.	PERCENT EFFICIENCY*	ΔP in. H <sub>2</sub> O	FILTER SIZE (CFM)	TEAM	DUE DATE	INSTALL. DATE	DUCT SIZE	VELOCITY (FPM)	CFM	BOX/ OPEN FACE
1	Loft N.E.	FGDE 1000/2000	>99.99	0.6	1000	3	06/07	02/19/1982	12	-	-	B
2	Loft E.M.	FPE-2000	>99.99	7.2			When Replaced	08/27/1997	-	-	-	
3			>99.99	7.1			When Replaced	08/27/1997	-	-	-	
4			>99.99	7.2			When Replaced	08/27/1997	-	-	-	
5			>99.99	7.0			When Replaced	08/27/1997	-	-	-	
6	↓	↓	>99.99	7.2			When Replaced	08/27/1997	-	-	-	
7	Loft E.M.	FPE-2000	>99.99	7.3			When Replaced	08/27/1997	-	-	-	
8	Loft S.E.	FHE-1000R	Inactive	N/S			When Activated	07/17/1990	Not Tested			
9	Loft N.C.	FHE-1000R	>99.99	0.9			06/07	09/01/1981	-	-	-	
10	↓	FHE-1000R	>99.99	0.9			06/07	09/01/1981	-	-	-	
11	↓	FHE-1000R	>99.99	0.9			06/07	09/01/1981	-	-	-	
12	Loft N.C.	FHE-1000R	>99.99	0.9			06/07	09/01/1981	-	-	-	
15	Loft S.W.	FPE-1R	>99.99	0.1			06/07	08/01/1997	~12x12	-	-	
16	Loft S.W.	FHE-3	>99.99 <sup>□</sup>	0.8	↓	↓	06/07	08/19/1999	12	-	1330	B
18	Roof N.C.	FHE-2	99.98	0.8	1000	3	06/07	01/16/2002	-	-	-	O

\* ACCEPTABLE EFFICIENCY >= 99.97%

REMARKS: Gross/Shroud Test in accordance with HEPA 1.0 (Latest Revision) E. = East, W. = West, N. = North, S. = South, C. = Center, Middle  
 O = Unit Passed penetration Test, yet Filter ΔP is over recommended Allowable of 5.0 in. H<sub>2</sub>O. recommend replacement  
 □ = No Smoke injection port available, used calculated 100% in <sup>WSS</sup> photometer circuitry.

CC:

LL 5531 (Rev 8/00)

SIGNED: Mark D. Indell

EXT. 3-6119

# LLNL HEPA Standards

- ES&H Manual Document 12.5 HEPA Filter System Design for LLNL Applications Section 2.6.5 states.
- HEPA filters shall be replaced when -  
pressure drop across a filter exceeds 5 inches w.g..

# Possible HEPA fix options

- Replace the filter arrangement with a bag-in/bag-out filter assembly with built-in test equipment, similar to what is in the BSL3.
- Order DOE-3020-05 compliant filters and specify closed housings when they're ordered (vendors supply the additional sides and duct stubs on request).
- Try to order like-for-like filters.

# Thursday June 8th

- AC mechanic and Heavy Equipment shop brought in to check exhaust fan and motor.
- Exhaust Fan and Motor determined OK.
- Determined HEPAS clogged.
- Official Stop work notice sent out by facility manager.
- Resident H&S tech discusses problem with back up tech- back up tech suggest he might know of some possible like- for- like HEPAs available.

# Friday June 9th

- BIO H&S back-up tech acquires new replacement HEPAs from facility that no longer needs them.
- Facility Manager and primary H&S tech write IWS for HEPA replacement.
- Start planning for job (equipment needed, personnel, other documentation).



# Monday June 12th

- IWS completed and authorized.
- Hazard Assessment and Control form completed by the Industrial Hygienist.
- H&S techs gather supplies for job.
- HEPA replacement team identified.



# Tuesday June 13th

- Pre-Start/ S.P.A. meeting.
- Gather additional equipment needed as determined during Pre-Start/ S.P.A. meeting.
- LOTO of supply and exhaust systems.
- Re-brief and discuss stopping points.
- **Start work and Complete HEPA replacement.**
- **Re-test HEPAs by IHIL. HEPAs pass**



# Wednesday June 14th

- AC mechanic re-balances air flow in B365.
- Technical Safety Services recertifies Bio-Safety Cabinets
- Chemical fume hoods verified operating properly.
- Installed Pre-filters...
- Building 365 Stop Work lifted by Facility Manager. Normal operations resume.



O: Christine Little

HAZARDS CONTROL — INDUSTRIAL HYGIENE INSTRUMENT LAB  
HEPA FILTER TEST RESULTS

PAGE 1 OF 1

LDG.: 365

PHOTOMETER HC # 0671

TEST/VISIT DATE 06/13/06

FILTER NO.	LOCATION	FAN NO.	PERCENT EFFICIENCY*	$\Delta P$ in. H <sub>2</sub> O	FILTER SIZE (CFM)	TEAM	DUE DATE	INSTALL. DATE	DUCT SIZE	VELOCITY (FPM)	CFM	BOX/ OPEN FACE
2	Loft E.M.	FFE-2000	99.99	1.5	1000	3	06/07	06/13/06	-	-	-	B
3	Loft E.M.		99.99	1.5				06/13/06	-	-	-	
4			99.99	1.5				06/13/06	-	-	-	
5			99.99	1.5				06/13/06	-	-	-	
6			99.99	1.5				06/13/06	-	-	-	
7	Loft E.M.	FFE-2000	>99.99	1.4	1000	3	06/07	06/13/06	-	-	-	B
<del>No Further Entries</del>												

\* ACCEPTABLE EFFICIENCY  $\geq$  99.97%

REMARKS: Gross/Shroud Test in accordance with HEPA 1.0 (Latest Revision)

C:

5531 (Rev 8/00)

SIGNED: Mark Dindell

EXT. 3-6119

# Photo Gallery of HEPA Change out

Crew:

Dione Ancheta

Robert Johnson

Todd Coble

Peggy Castello

# Git R' Done!



# Sample/Swipe Team



On the move.... To the lay  
down area



The belly of the monster...



Are we there yet?



# Where the Pre-filters should have gone!



# CREDITS

- H&S Team 3
  - Health & Safety Technicians
    - (Primary) Todd Coble
    - (Back-up) Robert Johnson
  - IH
    - (Primary) Christine Little
    - (Back-up) Paul Davis
- Chemistry
  - Mechanical Technician
    - Dione Ancheta
- H&S Team 2
  - Health & Safety Technician
    - Peggy Castello
- Plant Engineering
  - AC Mechanic - Bill Briggs
  - Heavy Equipment Shop – Eric Yeoman, Mike Castellanos

# Players Involved Continued...

- Biosciences Directorate
  - Patsy Gilbert, Select Agent Facility Manager
  - Frank Bailey , FPOC
  - Anselmo Duenas, Safety Officer
- Hazards Control- Safety Programs
  - IHIL- Bruce Bettencourt, Sterling Sawyer, and Mark Tindle
  - CBS HEPA SME- Gordon Miller
  - Respirator Services
- Outside Contractor
  - Technical Safety Services



# Opportunities for Learning...

- Safe Plan of Actions (SPAs)
- IWS Development
- Special Concerns for Biological Research Facilities
- New Health and Safety Technician cross training

This work was performed under the auspices of the U.S. Department of Energy by  
University of California,  
Lawrence Livermore National Laboratory under Contract W-7405-Eng-48